



16-Pin and 4-Pin
Connectors hardwired in
parallel to the same harness

TECINSpect® DIAGNOSTIC TOOL

REPLACES ALL OTHER VERSIONS OF TECMATE

The TECINSpect Diagnostic Tool is capable of providing simple, fast and accurate diagnostics of Genteq® Constant Airflow (Variable Speed) OEM indoor blower ECM models 2.0, 2.3, EON® & 3.0. These tools are designed for use only on Genteq ECM products including models previously branded GE and GE ECM by Regal™. The catalog number for the TECINSpect Diagnostic Tool is GA447.

Included with the TECINSpect Diagnostic Tool is our ECM Service Guide. It can also be downloaded from our website www.thedealertools.com or the DealerToolbelt app. The current guide includes:



- Complete diagnostics including the use and application of the TECINSpect Diagnostic Tool for all Genteq Constant Airflow (Variable Speed) OEM indoor blower ECM models.
- Complete diagnostics for Genteq Constant Torque OEM X13® and Endura® Pro indoor blower ECM models.
- Complete diagnostics for Genteq Constant Speed OEM outdoor fan ECM models 142 & 142^R.



Scan the QR code to get your free Dealer Toolbelt app or search for "Dealer Toolbelt" from your App store.



TECINspect® DIAGNOSTIC TOOL

The TECINspect Diagnostic Tool was previously branded TECMate PRO. The TECMate Pro and XL models are no longer in production. Below is a genealogy and compatibility quick reference chart.



	SWITCHES	CONNECTOR	APPLICABLE PRODUCTS	NOTES
TECMate XL	4	16-Pin	Models 2.0, 2.3, Eon & 3.0	16-4 Pin adapter required for 3.0
TECMate Pro (v1)	1	16-Pin	Models 2.0, 2.3, Eon & 3.0	16-4 Pin adapter required for 3.0
TECMate Pro (v2)	1	16-Pin	Models 2.0, 2.3, Eon & 3.0	16-4 Pin adapter included in kit
TECMate Pro (v3)	1	16 & 4 Pin	Models 2.0, 2.3, Eon & 3.0	
TECINspect	1	16 & 4 Pin	Models 2.0, 2.3, Eon & 3.0	Same as TECMate Pro (v3)

- Notes:
1. The 16-4 pin adapter was introduced with the TECMate Pro (v2). This adapter is available on our website TheDealerToolbox.com.
 2. With the 16-4 pin adapter, the TECMate Pro provides the same diagnostics as the TECINspect Diagnostic Tool.
 3. Model 2.5 is not compatible with the TECMate Pro or TECINspect Diagnostic Tool. Diagnostics for this motor are only available through the HVAC system manufacturer.



Genteq® X13®, Endura® Pro, 142 & 142^R ECM models are not compatible with the TECINspect Diagnostic Tool. However, these motors are easily diagnosed with a basic volt/ohm meter using the ECM Service Guide. Diagnostics for all Evergreen® products are included in their respective installation guides.



Regal Beloit America, Inc.
 1325 Heil Quaker Blvd.
 LaVergne, TN 37086
 PH: 800-672-6495
 FAX: 800-468-2062

thedealertools.com

