


Replacement Parts List

00e[®] VR Series

SUPERSEDES: NEW


EFFECTIVE: June 10, 2022

VR15L, M, H to VR 25L, M & VR30L



Model	Rotating Assembly	Motor Control Board	Conduit Connector	Communications Module	Gasket and Bolt Kit
	Part Number	Part Number	Part Number	Part Number	Part Number
	A, B, C	D		E	A
VR15L-F	975-430RP	975-441RP	975-461RP	975-456RP	975-486RP
VR15M-F		975-442RP			
VR15H-F	975-431RP	975-443RP			
VR20L-F	975-432RP	975-444RP			
VR20M-F	975-433RP	975-445RP			
VR20H-F	975-434RP	975-446RP			
VR25L-F	975-435RP	975-447RP			
VR25M-F	975-436RP	975-448RP			
VR30L-F	975-437RP	975-450RP			
VR15L-SF	975-430RP	975-441RP			
VR15M-SF		975-442RP			
VR15H-SF	975-431RP	975-443RP			
VR20L-SF	975-432RP	975-444RP			
VR20M-SF	975-433RP	975-445RP			
VR20H-SF	975-434RP	975-446RP			
VR25L-SF	975-435RP	975-447RP			
VR25M-SF	975-436RP	975-448RP			
VR30L-SF	975-437RP	975-450RP			

VR25H & VR30M, H



Model	Rotating Assembly	Motor Control Board	Conduit Connector	Gasket and Bolt Kit
	Part Number	Part Number	Part Number	Part Number
	A, B, C	D		A
VR25H-F	975-454RP	975-449RP	975-424RP	975-486RP
VR30M-F	975-455RP	975-451RP	975-424RP	
VR30H-F		975-452RP		
VR25H-SF	975-454RP	975-449RP	975-424RP	
VR30M-SF	975-455RP	975-451RP	975-424RP	
VR30H-SF		975-452RP		

Taco Comfort Solutions® A Taco Family Company

Taco, Inc., 1160 Cranston Street, Cranston, RI 02920 | Tel: (401) 942-8000

Taco (Canada), Ltd., 8450 Lawson Road, Suite #3, Milton, Ontario L9T 0J8 | Tel: (905) 564-9422

Visit our web site: www.TacoComfort.com | Printed in USA | ©2022 Taco, Inc.

